

Square Punch

- ▲ When punching a square hole there will be a slight burr on the back side of hole. If this is not permissible a sanding op may be added @ a cost
- ▲ Square holes will be on center to the wire $\pm .015$ if center is implied
- ▲ Punch break out applies to all punched shapes (See Punch Break out)

